




1. TAB OF COVER TIE IS INSERTED INTO HOLE IN BASE.
2. WASHERS AND NUTS ARE MANUALLY ASSEMBLED ONTO STUD AND NUTS ARE FINGER TIGHTENED ANYWHERE BELOW TOP OF STUD.
3. TORQUE REQUIRED FOR HEX NUT IN USER APPLICATION TO BE 4.0 - 5.0 NEWTON METERS (35-44 IN-LBS).

- # METRIC

[illegible]